



SIRIM QAS International Sdn. Bhd. (Company No. 410334-X)
No. 1, Persiaran Dato' Menteri, P.O. Box 7035, Section 2
40911 Shah Alam, Selangor Darul Ehsan, Malaysia
Tel: 03-55445853 / 55445854
Fax: 03-55445855

TEST REPORT

REPORT NO : 2008CB1484

PAGE : 1 OF 2

This Test Report refers only to samples submitted by the applicant to SIRIM QAS International Sdn. Bhd. and tested by SIRIM QAS International Sdn. Bhd. This test report shall not be reproduced, except in full and shall not be used for advertising purposes by any means or forms without written approval from Executive Director, SIRIM QAS International Sdn. Bhd. Please refer overleaf for Conditions Relating To The Use of Test Report.

Applicant. : MTL PRODUCTS MARKETING SDN. BHD.
S 111, Jalan Dato Haji 3,
Taman Dato' Yan Yew Lai,
Batu 6 Jalan Puchong,
58200 Kuala Lumpur.

Manufacturer : - Nil -

Product : MTL Mushroom Bolt c/w Steel Bracket & Nut

Reference Standard/
Method of test : Company's Specification – Breaking Load Test

Description of sample : One sample of MTL Mushroom Bolt c/w Steel Bracket & Nut was received for testing.
Serial No. : 80048


Date received : 22 / 09/ 2008

Job No./Ref. No. : J20085041395 / SQAS/CBMT/T.REC/MSL/ 03

Issued date : 13 OCT 2008

Approved Signatories

(MOHD. AMIR ABDULLAH)
Technical Executive



(YM RAJA NOR SIHA RAJA ABD. HANAN)

Group Leader
Civil & Construction Section
Product Certification, Inspection & Testing Department

TEST REPORT

REPORT NO : 2008CB1484	PAGE : 2 OF 2
This Test Report refers only to samples submitted by the applicant to SIRIM QAS International Sdn. Bhd. and tested by SIRIM QAS International Sdn. Bhd. This test report shall not be reproduced, except in full and shall not be used for advertising purposes by any means or forms without written approval from Executive Director, SIRIM QAS International Sdn. Bhd.	

TEST RESULTS : BREAKING LOAD TEST

TEST SPEED : 5 mm/min

SAMPLE REFERENCE	BREAKING LOAD, (kN)	OBSERVATION / REMARKS
MTL Mushroom Bolt c/w Steel Bracket & Nut Serial No. : 80048	5.23	Bolt thread sheared




Photo 1.0 : Shows sample during test.




Photo 2.0 : Shows sample after test.



13 OCT 2008