

SIRIM QAS International Sdn.Bhd. (Company No.: 410334-X)

No. 1, Persiaran Dato' Menteri, P.O. Box 7035, Section 2

40911 Shah Alam, Selangor Darul Ehsan, Malaysia Tel. no : 03-55445853 / 55445854

Fax no.: 03-55445855

## TEST REPORT

REPORT NO: 2008CB1317

PAGE:

OF

2

This Test Report refers only to samples submitted by the applicant to SIRIM QAS International Sdn. Bhd. and tested by SIRIM QAS International Sdn. Bhd. This test report shall not be reproduced, except in full and shall not be used for advertising purposes by any means or forms without written approval from Executive Director, SIRIM QAS International Sdn. Bhd. Please refer overleaf for Conditions Relating To The Use of Test Report.

Applicant

MTL PRODUCTS MARKETING SDN. BHD.

S 111 Jalan Dato Haji 3, Taman Dato Yan Yew Lai, Batu 6 Jalan Puchong, 58200 Kuala Lumpur.

Manufacturer

- Nil -

Product

MTL Heavy Duty (S/Steel Clad) Adjustable Foot Insert.

Reference Standard/

Company's Specification: Compression Load Test.

Method of test

Description of sample

One sample of MTL Heavy Duty (S/Steel Clad) Adjustable Foot Insert was

received for testing. Serial No.: 80063

Date received

18/08/2008

Job no./Ref. no.

J20085041237 / SQAS / CBMT / T.REC / MSL / 05

Issued date

2 5 AUG 2008

civil macructi Section

Approved Signatories

(MOHD AMIR ABDULLAH)

Technical Executive

(YM RAJA NOR SIHA RAJA ABD. HANAN)

Group Leader

Civil & Construction Section

Product Certification, Inspection & Testing Department

## **TEST REPORT**

This Test Report refers only to samples submitted by the applicant to SIRIM QAS International Sdn. Bhd. and tested by SIRIM QAS International Sdn. Bhd. This test report shall not be reproduced, except in full and shall not be used for advertising purposes by any means or forms without written approval from Executive Director, SIRIM QAS International Sdn. Bhd.

## **TEST RESULTS: COMPRESSION LOAD TEST**

SAMPLE REFERENCE	OBSERVATION / REMARKS
MTL Heavy Duty (S/Steel Clad) Adjustable Foot Insert	- Maximum load 32.10 kN load.
Serial No.: 80063	- The ring at the base fractured. (See photo 2.0)




Photo 1.0: Show sample during test




Photo 2.0: Show sample after test

Civil Section Section

Th

2 5 AUG 2008